

**V1.2**

## **3DMAKERPRO**

f @3DMakerProCares

@official3DMakerPro

@3DMakerPro

<https://store.3dmakerpro.com/>

service@3dmakerpro.com

## **JimuMeta**

f @JimuMeta

@JimuMeta


<https://www.jimumeta.com/>

service@jimumeta.com



**3DMAKERPRO**


<https://store.3dmakerpro.com/>



# **Tripod for Mole**

3D MAKERPRO LIMITED

# HARDWARE CONNECTION



Connect the tripod to the extension rod by inserting the screw thread on the top into the screw hole in the another and tighten it clockwise;  
connect the two to the ball head with the same operation;  
then connect the whole tripod to the scanner body through its bottom hole as shown in the picture.  
Note: The extension rod can be installed or not as you wish.